

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329



Industrial Services for Industry



Diesal parts
carbide coated to improve wear resistance to sand



48-inch fan
coated with .030 420SS for wear resistance



Heavy duty cylinder
manufactured to specifications



Large compressor cylinder
rebuilt ID with 420SS



Press flywheel
repaired bearing bores



20-inch cylinder, rod and piston
repaired to specifications



Air compressor rods, cylinder, and pistons
totally rebuilt



Large fan shaft
repaired bearing areas and center section

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329



Industrial Services for Industry



Gearbox
rebuilt bearing bores and shaft seal area



Punch press flywheel and shaft
repaired to specification



Machine tool spindle
repaired bearing and seal areas



Pump housings
rebuilt by welding and thermal sprayed coatings



Eccentric shaft for foundry shaker
repaired bearings and seal area



Broken gear box
repaired (foreign unit)



Large gear
replaced four teeth and recut



Material handling fan
repaired bearing areas and fan blades