

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329



Industrial Services for the Plastics and Rubber Industries



Extruder feed box
rebuilt to specifications



Shaft
laser hardened tapered bearing area to 58-60Rc



Small granulator rotor
repaired bearing areas



Granulator frame
rebuilt bearing bores and knife bed



Large twin paddle mixer
rebuilt to specifications



Gear box
rebuilt bearing bores and shaft seal areas



Large gear for rubber press
rework bearing area



Large granulator shaft
replaced broken end

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329



Industrial Services for the Plastics and Rubber Industries



Mixer paddles
machined bearing and seal areas



large granulator rotor
reworked bearing areas and knife bed area



Large rotary feed valve
manufactured to specifications



rubber mill
being disassembled for total rebuild



24-inch hydraulic piston
ram area built up with 420SS and ground to size



air compressor rods, cylinder and pistons
totally rebuilt to specifications



Large housing
rebuilt bearing bores



Stainless steel lid
modified for large mixer