

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329



Industrial Services for the Wire Industry



Large machine housing
rebuilt bearing bores




Morgan top hats
completely rebuilt



Broken block--repaired and coated
with 420 stainless and finished



Mill shafts
laser hardened bearing seat



Flattening mill assemblies
carbide inserts ground and polished to 6-8Ra



Flattening mill assembly
rebuilt bearing and seal areas



Wire capstans
carbide coated and finished



10-step capstan
rebuilt to size with 420SS, carbide coated and finished

Light Beam Technology, Inc.
7416 W15th Avenue
Gary, Indiana 46406
phone 219-944-8801 fax 219-944-8819

Boyd Machine & Repair, Inc.
P. O. Box 93
Wolf Lake, Indiana 46796
phone 260-635-2195 fax 260-635-2329




Industrial Services for the Wire Industry



10" diameter V sheaves
fused coating 60 Rc



40" diameter block,
coated with 420 stainless and finished



26" diameter block, carbide coated
and finished to 12-16RA



68" diameter wire coiler wheel
built up with 420SS and finished



Gear box
rebuilt bearing bores and shaft seal areas



40" diameter shaver block
laser clad with NiCrBr 60Rc



48" diameter block
weld overlay and finish ground



2-step 48-60" diameter coiler wheel,
built up with 420 stainless and finished